

FIRM NAME Bell Telephone Maintenance Center

ADDRESS \_\_\_\_\_ TELEPHONE \_\_\_\_\_

PERSONNEL CONTACTED Mr. Don Rand POSITION \_\_\_\_\_

POSITION \_\_\_\_\_

POSITION \_\_\_\_\_

ACTION INITIATED BY: \_\_\_\_\_

(1) Inspection of maintenance center June 21, 1972  
by R. Lyman + R. Carson of Sanitary Services  
map included shows findings of inspection.

(2) MR. DON RAND CONTACTED - JUNE 26, 1972 - SAID OIL IS NOW STORED AND  
HAULED TO FRIENDS IN ARKANSAS FOR DRIVEWAY.

Southwestern Bell Telephone Co.  
3028 S. Fremont  
Springfield, Mo. 65804  
January 6, 1976

J. Randall Lyman  
Water Pollution Control Inspector  
Surveillance & Enforcement  
City Of Springfield  
830 Boonville Ave.  
Springfield, Mo. 65802

Dear Mr. Lyman:

In reference to your letter of December 29, 1975, the problems referred to in your letter have all been remedied. This work was completed on January 6, 1976 by the Reed Plumbing Co.

If you wish to inspect the work performed, and/or have any further recommendations, please contact me at this office.

*Gerald W. Cole*  
Gerald W. Cole  
Chief Switchman


3028 S. FREMONT



Bell Telephone Maintenance Center

Don Rand --Contract for Maintenance  
has it hauled off? maybe  
883-8764-must call or contact.

Runoff from fuel pump and oil barrels to storm sewer. (dike needed?)  
Floor drains in shop flow directly to storm sewer.



To Randy

Date 12/22 Time 1:30 By \_\_\_\_\_

## While You Were Out

Mr. Terry Cole

of S.W. Bell Tel.

☒ Telephoned

☐ Called to See You

☐ Will Call Again

☐ Wants to See You


☒ Please Call Him

☐ Rush!

Phone 881-9875

Message Terry Cole

→ 3028 S. Fremont

 to septic TANK

Overflow to Sewer

97' to 94.5'

*Vertical signature/initials*



December 29, 1975

Mr. Gerald W. Cole, Maintenance Engineer  
Southwestern Bell Telephone Company  
3028 South Fremont  
Springfield, Missouri 65804

Dear Mr. Cole:

On a recent inspection of the sanitary facilities at 3028 South Fremont, some problems were revealed concerning the pressure line serving this facility. An enclosed print notes the approximate locations of the problems. At the cleanout number four (4) it appears that a lawnmower has hit and chipped a hole in the cleanout. Also, at cleanout number two (2) the cleanout tee appears to be loose, and at cleanout number one (1) the cleanout is completely broken off. When the sewage lift pump(s) activates, raw sewage is forced out into or onto the ground. These problems need to be remedied as soon as possible, and measures should be taken to avoid a recurrence. Please contact this office, in writing, within fourteen (14) days indicating your plans for abatement of these problems.

If we can be of any assistance or can answer any questions, please do not hesitate to call.

Yours truly,

*J. Randall Lyman*  
J. Randall Lyman  
Water Pollution Control Inspector  
Surveillance and Enforcement

JRL:cc

Enclosure

ccs: John Nixon, Missouri Department of Natural Resources  
Public Works File  
Harold Bengsch, Health Department

3028 S. Fremont



June 21, 1972

Mr. Don Rand was contacted and asked what was done with the used oil. He said that until a year ago he dumped it on the back of the lot and it might have entered the storm sewer. Now he collects it in 55 gal. drums and stores it near the gas pumps and takes it to some friends house in Arkansas who puts it on their driveway to eliminate dust.

Randy Lyman

3028 S. Fremont